
Urgent!

Field Safety Notice (FSN)



July 24th, 2018

FSCA Number: FSCA-2018-07-18

FSCA Title: HCU 40 Leaking Vacuum Valve

Affected Product: Heater-Cooler Unit HCU 40

Affected product details: Following serial numbers of the above mentioned device are affected by this FSCA:

- S/N 90440387 to 90440728
- S/N 90440366.

Description of the problem:

Dear valued colleagues and business partners,
The HCU 40 Heater-Cooler Unit is intended for cooling or warming a patient connected to the extracorporeal perfusion circuit and keeping the required patient temperature constant.

The system comprises two separate water circuits with temperature regulation. The first circuit is for connecting the oxygenator heat exchanger and/or the warming/cooling blanket, the second circuit is intended for connecting the cardioplegia heat exchanger.

Both water circuits of the HCU 40 feature multiple valves that control the water flow. One of these valves is the vacuum valve. The vacuum valve is located in both, the patient and the cardioplegia water circuit.

Maquet Cardiopulmonary has received complaints in relation to device malfunctions caused by leaking vacuum valves.

Corrective Action:

Replacement of the vacuum valves in patient and cardioplegia water circuit of the affected HCU 40 systems.

Advice on action to be taken by the user:

- According to our post-market surveillance documentation, your current stock may include products affected by this action.
- The update on your HCU 40 systems has to be performed by authorized Getinge service personnel.
- Fill out the enclosed Letter of Acknowledgement and return it as soon as possible to your local Getinge representative by mentioning FSCA-2018-07-18 as reference.

Referenced document/attachment:

- Letter of Acknowledgement

Transmission of the Field Safety Notice:


- This notice needs to be passed on to all those who need to be aware within your organization or to any organization where the potentially affected devices have been transferred.
- Please transfer this notice to other organizations on which the action has an impact.
- Please maintain awareness on the notice and resulting actions for an appropriate period to ensure effectiveness of the corrective action.
- According to our post-market surveillance documentation the following countries are directly affected by this FSCA: AE, AU, CA, CL, CN, CU, CZ, DE, DK, EG, ES, FI, GB, IE, IN, IQ, IT, JO, KE, LB, MA, MX, NG, NL, PK, PL, PT, RS, RU, SA, SE, SG, TH, TR.

We apologize for any inconvenience this may cause you and we will do our utmost to carry through this action as swiftly as possible.

As required, we have provided this notification to the necessary Regulatory Agencies.

Should you have questions or require additional information, please contact your local Getinge representative.

Sincerely,



Maquet Cardiopulmonary GmbH
Kehler Str. 31
76437 Rastatt
GERMANY